



EROSION AT SOUTHWEST CORNER, LOSS OF RIPRAP AND FILL



EROSION AT NORTHWEST CORNER



POSSIBLE WIER JUST DOWNSTREAM, DAMAGED