



**EROSION BEHIND SOUTH ABUTMENT**

**DRIFT ON RAIL,  
LOOKING SOUTHEAST**



**DRIFT IN SUPERSTRUCTURE,  
LOOKING SOUTH**