



**EROSION OF SOUTH BERM,
LOOKING WEST,
WATER TO 2' ABOVE LOW
SUPERSTRUCTURE**

**NORTHWEST BANK EROSION,
LOOKING NORTH**



**UNDERMINED NORTH ABUTMENT FOOTING,
LOOKING NORTH**