



DRIFT ON UPSTREAM SIDE OF BRIDGE

**UNDERMINED NORTH ABUTMENT
FOOTING,
LOOKING NORTH**



DETERIORATION OF PIER ENCASEMENTS