



**CRACKED SOUTHEAST WING,
LOOKING SOUTH**



**CRACKED BACKWALL AND
DETERIORATED SOUTHWEST
TRUSS BEARING,
LOOKING SOUTH**



**DRIFT IN SUPERSTRUCTURE,
LOOKING NORTHEAST**