



**VERY POOR AND DETERIORATED
SOUTHWEST TRUSS BEARING,
LOOKING SOUTHEAST**

**ROCK STREAM BOTTOM,
LOOKING NORTH**

