



**CRUMBLING AND BROKEN SOUTH
ABUTMENT,
LOOKING WEST**

**SIDE VIEW LOOKING NORTHWEST, NOTE
ELECTRICAL CABLE ON BRIDGE,
POSSIBLE ELECTRICAL SHORT**

