



**EROSION AT NORTHEAST CORNER,
LOOKING SOUTHEAST**



**DRIFT IN TRUSS,
LOOKING SOUTHEAST**



**CORRODED AND RIPPLED SOUTH TRUSS,
TOP CHORD**