



**EROSION AT EAST BACKWALL,
LOOKING EAST**

**FLEXING WEST ABUTMENT PILE,
LOOKING NORTH**

