



**EROSION AT SOUTH ABUTMENT,
LOOKING SOUTHWEST, LOSS OF 3' OF
FILL**

**EROSION AT NORTH ABUTMENT,
LOOKING WEST, LOSS OF 2' OF FILL**

